

FIG.1





FIG.2







FIG.4





**FIG.5**

FIG.6



T010503-T010504-9360

FIG.7




FIG.8




FIG.9




FIG.10




FIG.11

TOKYO ELECTRON







FIG. 12



**FIG.13**

**FIG.14**


FOTOGO-TELEFON

# FIG.15

		STATUS OF POWER SOURCE	
		EXTERNAL POWER MODE	INTERNAL POWER SOURCE MODE
ERROR CONTENTS	ERROR IN SOFTWARE PROCESSING	L TIMES	M TIMES
	NO RESPONSE FROM THE OTHER PARTY	L TIMES	N TIMES


WHERE  $N < M < L$

FIG.16



TOTO50-T050-EE549860

FIG.17



## FIG.18

		STATUS OF POWER SOURCE	
		EXTERNAL POWER MODE	INTERNAL POWER SOURCE MODE
ERROR CONTENTS	ERROR IN SOFTWARE PROCESSING	t1	t2
	NO RESPONSE FROM THE OTHERPARTY	t2	t2

WHERE  $t_1 < t_2$


**FIG.19**

FIG.20

